

Beulah Heights Elementary

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
BH1	12/5/2017	6:00 AM	SC-1S	<1.00	402	<500	10.9	315	Backflow	No Action Taken
BH2	12/5/2017	6:16 AM	SC-1M	<1.00	320	<500	4.85	125	Backflow	No Action Taken
BH3-L	12/5/2017	6:07 AM	DFD	<1.00	48.8	<500	2.04	116	Main hallway	No Action Taken
BH3-R	12/5/2017	6:08 AM	DFD	<1.00	104	<500	3.69	150	Main hallway	No Action Taken
BH4	12/5/2017	6:09 AM	KSF	<1.00	325	<500	9.40	1600	Nurses office	No Action Taken
BH5-L	12/5/2017	6:11 AM	DFD	<1.00	355	<500	17.9	802	Main north hallway	Disabled
BH5-R	12/5/2017	6:12 AM	DFD	<1.00	94.8	<500	5.82	514	Main north hallway	No Action Taken
BH6	12/5/2017	6:15 AM	TL	<1.00	306	<500	<1.00	35.1	Teachers Lounge	No Action Taken
BH7-L	12/5/2017	6:16 AM	DFD	<1.00	120	<500	9.94	525	Southeast hallway	No Action Taken
BH7-R	12/5/2017	6:17 AM	DFD	<1.00	56.5	<500	2.93	70.4	Southeast hallway	No Action Taken
BH8-L	12/5/2017	6:18 AM	DFD	<1.00	147	<500	10.0	328	Gymnasium	No Action Taken
BH8-R	12/5/2017	6:19 AM	DFD	<1.00	106	<500	7.51	166	Gymnasium	No Action Taken
BH9-L	12/5/2017	6:23 AM	DFD	<1.00	506	<500	18.1	869	Cafeteria	Disabled
BH9-R	12/5/2017	6:23 AM	DFD	<1.00	575	<500	8.24	915	Cafeteria	No Action Taken
BH10	12/5/2017	6:24 AM	KSF	<1.00	116	<500	3.09	947	Kitchen sink	No Action Taken
BH11	12/5/2017	6:25 AM	TL	<1.00	1420	<500	2.07	487	South Teachers Lounge	No Action Taken
SL 15SEC	12/5/2017	5:52 AM		<1.00	24.8	<500	1.23	7.51	Meter	No Action Taken
SL 45SEC	12/5/2017	5:52 AM		<1.00	13.1	<500	<1.00	5.96	Meter	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water