

Heritage Elementary

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
HRT1	4/3/2018	5:48 AM	SC-1S	<1.00	55.9	<500	<1.00	15.3	Backflow #1	No Action Taken
HRT2	4/3/2018	5:51 AM	SC-1M	<1.00	9.33	<500	<1.00	2.45	Backflow #2	No Action Taken
HRT3	4/3/2018	5:53 AM	DFS	<1.00	214	<500	<1.00	4.80	Hallway near Classroom #112	No Action Taken
HRT4-L	4/3/2018	5:56 AM	KSF	<1.00	279	<500	2.14	702	Classroom #104	No Action Taken
HRT4-R	4/3/2018	5:57 AM	DFS	<1.00	256	<500	<1.00	71.5	Classroom #104	No Action Taken
HRT5-L	4/3/2018	5:58 AM	KSF	<1.00	325	<500	1.28	103	Classroom #102	No Action Taken
HRT5-R	4/3/2018	5:58 AM	DFS	<1.00	561	<500	<1.00	205	Classroom #102	No Action Taken
HRT6-L	4/3/2018	6:00 AM	KSF	<1.00	413	<500	1.28	1150	Classroom #102	No Action Taken
HRT6-R	4/3/2018	6:01 AM	DFS	<1.00	277	<500	<1.00	128	Classroom #102	No Action Taken
HRT7	4/3/2018	6:02 AM	FF	<1.00	291	<500	1.04	1310	Main Office	No Action Taken
HRT8	4/3/2018	6:03 AM	TL	<1.00	999	<500	<1.00	502	Teachers Lounge	No Action Taken
HRT9-L	4/3/2018	6:05 AM	KSF	<1.00	517	<500	<1.00	414	Kitchen	No Action Taken
HRT9-R	4/3/2018	6:06 AM	KSF	<1.00	543	<500	1.36	630	Kitchen	No Action Taken
HRT10	4/3/2018	6:07 AM	DFS	<1.00	463	<500	<1.00	670	Cafeteria	No Action Taken
HRT11	4/3/2018	6:08 AM	DFS	<1.00	282	<500	<1.00	184	Hallway near Gymnasium	No Action Taken
HRT12	4/3/2018	6:09 AM	DFS	<1.00	743	<500	<1.00	42.7	Hallway near Classroom # 214	No Action Taken
SL 15SEC	4/3/2018	5:47 AM		<1.00	47.5	<500	1.54	12.1	Meter	No Action Taken
SL 45SEC	4/3/2018	5:47 AM		<1.00	25.5	<500	<1.00	4.10	Meter	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water