

BELMONT ELEMENTARY SCHOOL

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
BT1	1/24/2018	6:19 AM	SC-1S	<1.00	25.6	<500	<1.00	32.0	Backflow #1	No Action Taken
BT2	1/24/2018	6:24 AM	SC-1M	<1.00	26.1	<500	<1.00	8.84	Backflow #2	No Action Taken
BT3-L	1/24/2018	6:25 AM	DFD	<1.00	97.4	<500	4.69	147	Main Hallway Near Restrooms	No Action Taken
BT3-R	1/24/2018	6:26 AM	DFD	<1.00	96.1	<500	1.45	72.7	Main Hallway Near Restrooms	No Action Taken
BT4	1/24/2018	6:28 AM	SF	<1.00	556	<500	1.28	175	Main Office	No Action Taken
BT5-L	1/24/2018	6:29 AM	DFD	<1.00	238	<500	3.25	311	Kindergarten Classroom	No Action Taken
BT5-R	1/24/2018	6:30 AM	DFD	<1.00	287	<500	4.04	346	Kindergarten Classroom	No Action Taken
BT6	1/24/2018	6:31 AM	DFS	<1.00	104	<500	<1.00	5.84	Hallway Outside Gymnasium	No Action Taken
BT7	1/24/2018	6:32 AM	DFS	<1.00	134	<500	<1.00	12.9	Hallway Outside Gymnasium	No Action Taken
BT8	1/24/2018	6:33 AM	TL	<1.00	742	<500	4.33	660	Teachers Lounge	No Action Taken
BT9-L	1/24/2018	6:34 AM	DFD	<1.00	277	<500	5.29	203	Cafeteria	No Action Taken
BT9-R	1/24/2018	6:35 AM	DFD	<1.00	149	<500	2.95	61.9	Cafeteria	No Action Taken
BT10	1/24/2018	6:36 AM	KS	<1.00	299	<500	<1.00	2110	Kitchen Sink	No Action Taken
SL 15SEC	1/24/2018	5:55 AM		<1.00	18.9	<500	1.06	12.1	Water Meter	No Action Taken
SL 45SEC	1/24/2018	5:55 AM		<1.00	14.3	<500	1.99	12.0	Water Meter	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water