

Carlile Elementary School

| Sample ID | Sample Date | Sample Time | Fixture Type | Cadmium (ppb) | Copper (ppb) | Iron (ppb) | Lead (ppb) | Zinc (ppb) | Location | Action |
|-----------|-------------|-------------|--------------|---------------|--------------|------------|------------|------------|--|--|
| CRL1-L | 9/13/2017 | 6:23 AM | DFD | <1.00 | 275 | <500 | <1.00 | 293 | Cafeteria Drinking Fountain (left) | No Action Required |
| CRL1-R | 9/13/2017 | 6:24 AM | DFD | <1.00 | 400 | <500 | 1.90 | 403 | Cafeteria Drinking Fountain (right) | No Action Required |
| CRL2 | 9/13/2017 | 6:27 AM | KSF | <1.00 | 541 | <500 | 15.6 | 1378 | Kitchen Sink Faucet | Replacing Faucet, Pipe & Shut Off Valves |
| CRL3 | 9/13/2017 | 6:30 AM | TLF | <1.00 | 572 | <500 | <1.00 | 245 | Teacher Lounge Sink Faucet | No Action Required |
| CRL4-L | 9/13/2017 | 6:32 AM | DFD | <1.00 | 25.7 | <500 | <1.00 | 548 | 1st Floor North Hall Drinking Fountain (left) | No Action Required |
| CRL4-R | 9/13/2017 | 6:33 AM | DFD | <1.00 | 174 | <500 | 1.36 | 298 | 1st Floor North Hall Drinking Fountain (right) | No Action Required |
| CRL5-L | 9/13/2017 | 6:34 AM | DFD | <1.00 | 303 | <500 | 2.04 | 457 | 1st Floor Mid-Hall Drinking Fountain (left) | No Action Required |
| CRL5-R | 9/13/2017 | 6:36 AM | DFD | <1.00 | 144 | <500 | <1.00 | 360 | 1st Floor Mid-Hall Drinking Fountain (right) | No Action Required |
| CRL6-L | 9/13/2017 | 6:37 AM | DFD | <1.00 | 205 | <500 | <1.00 | 328 | 1st Floor South Hall Drinking Fountain (left) | No Action Required |
| CRL6-R | 9/13/2017 | 6:38 AM | DFD | <1.00 | 105 | 580 | <1.00 | 141 | 1st Floor South Hall Drinking Fountain (right) | No Action Required |
| CRL7-L | 9/13/2017 | 6:40 AM | DFD | 1.00 | 373 | <500 | 2.10 | 716 | 2nd Floor North Hall Drinking Fountain (left) | No Action Required |
| CRL7-R | 9/13/2017 | 6:42 AM | DFD | <1.00 | 263 | <500 | 1.39 | 330 | 2nd Floor North Hall Drinking Fountain (right) | No Action Required |
| CRL8-L | 9/13/2017 | 6:45 AM | DFD | <1.00 | 230 | <500 | <1.00 | 505 | 2nd Floor South Hall Drinking Fountain (left) | No Action Required |
| CRL8-R | 9/13/2017 | 6:46 AM | DFD | <1.00 | 127 | <500 | <1.00 | 341 | 2nd Floor South Hall Drinking Fountain (right) | No Action Required |
| CRL9 | 9/13/2017 | 6:48 AM | DFS | <1.00 | 285 | <500 | <1.00 | 495 | Gym Drinking Fountain (left) | No Action Required |
| CRL10 | 9/13/2017 | 6:49 AM | DFS | <1.00 | 198 | <500 | 4.16 | 482 | Gym Drinking Fountain (mid) | No Action Required |
| CRL11 | 9/13/2017 | 6:50 AM | DFS | <1.00 | 155 | <500 | <1.00 | 108 | Gym Drinking Fountain (right) | No Action Required |
| CRL12-L | 9/13/2017 | 6:51 AM | DFD | 8.47 | 54.0 | <500 | 1.37 | 2905 | Pre-K Hall Drinking Fountain (left) | Disabled |
| CRL12-R | 9/13/2017 | 6:52 AM | DFD | 7.98 | 71.8 | <500 | <1.00 | 1626 | Pre-K Hall Drinking Fountain (right) | Disabled |
| CRL13-L | 9/13/2017 | 6:53 AM | DFD | 11.1 | 14.7 | <500 | <1.00 | 2562 | Kinder Hall Drinking Fountain (left) | Disabled |
| CRL13-R | 9/13/2017 | 6:54 AM | DFD | 5.67 | 11.3 | <500 | <1.00 | 1656 | Kinder Hall Drinking Fountain (right) | Disabled |
| CRL14 | 9/13/2017 | 6:56 AM | DFS | <1.00 | 851 | <500 | <1.00 | 303 | Music Room Hall Drinking Fountain | No Action Required |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, SC - Service Connection; KS - Kitchen Sink; TL - Teachers Lounge Sink