

COLUMBIAN ELEMENTARY SCHOOL

| Sample ID | Sample Date | Sample Time | Fixture Type | Cadmium (ppb) | Copper (ppb) | Iron (ppb) | Lead (ppb) | Zinc (ppb) | Location | Action |
|-----------|-------------|-------------|--------------|---------------|--------------|------------|------------|------------|----------------------------------|-----------------|
| COL1 | 1/30/2018 | 5:59 AM | SC-1S | <1.00 | 126 | <500 | 2.60 | 49.9 | Backflow Valve #1 | No Action Taken |
| COL2 | 1/30/2018 | 6:05 AM | SC-1M | <1.00 | 51.9 | <500 | <1.00 | 12.7 | Backflow Valve #2 | No Action Taken |
| COL3 | 1/30/2018 | 6:06 AM | TL | <1.00 | 158 | <500 | <1.00 | 886 | Teachers Lounge | No Action Taken |
| COL4 | 1/30/2018 | 6:08 AM | KSF | <1.00 | 445 | <500 | 1.56 | 76.0 | Classroom #24 | No Action Taken |
| COL5 | 1/30/2018 | 6:10 AM | DFS | <1.00 | 282 | <500 | <1.00 | 81.7 | South Hallway Near Classroom #34 | No Action Taken |
| COL6 | 1/30/2018 | 6:11 AM | DFS | <1.00 | 311 | <500 | <1.00 | 13.4 | Hallway Near Gymnasium | No Action Taken |
| COL7 | 1/30/2018 | 6:12 AM | DFS | <1.00 | 253 | <500 | 1.47 | 203 | Hallway Near Gymnasium | No Action Taken |
| COL8 | 1/30/2018 | 6:14 AM | DFS | <1.00 | 240 | <500 | <1.00 | 18.2 | Gymnasium | No Action Taken |
| COL9 | 1/30/2018 | 6:15 AM | DFS | <1.00 | 438 | <500 | <1.00 | 19.0 | Gymnasium | No Action Taken |
| COL10 | 1/30/2018 | 6:17 AM | DFS | <1.00 | 1020 | <500 | 10.6 | 458 | Cafeteria | No Action Taken |
| COL11 | 1/30/2018 | 6:19 AM | KSF | <1.00 | 234 | <500 | <1.00 | 307 | Kitchen | No Action Taken |
| COL12 | 1/30/2018 | 6:20 AM | DFS | <1.00 | 246 | <500 | <1.00 | 56.2 | Office Corridor | No Action Taken |
| COL13 | 1/30/2018 | 6:21 AM | DFS | <1.00 | 281 | <500 | <1.00 | 11.8 | Office Corridor | No Action Taken |
| COL14 | 1/30/2018 | 6:23 AM | KSF | <1.00 | 558 | <500 | <1.00 | 388 | Main Office | No Action Taken |
| | | | | | | | | | | |
| SL 15SEC | 1/30/2018 | 5:53 AM | | <1.00 | 24.1 | <500 | <1.00 | 32.9 | Meter | No Action Taken |
| SL 45SEC | 1/30/2018 | 5:53 AM | | <1.00 | 14.2 | <500 | <1.00 | 15.1 | Meter | No Action Taken |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water