

**CORWIN IMS**

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
CIMS1	12/12/2017	6:10 AM	SC-1S	<1.00	45.7	<500	<1.00	52.9	Backflow #1	No Action Taken
CIMS2	12/12/2017	6:14 AM	SC-1M	<1.00	49.0	<500	<1.00	85.9	Backflow #2	No Action Taken
CIMS3-L	12/12/2017	6:17 AM	DFD	<1.00	317	<500	<1.00	241	First Floor North Hallway	No Action Taken
CIMS3-R	12/12/2017	6:18 AM	DFD	<1.00	100	<500	<1.00	163	First Floor North Hallway	No Action Taken
CIMS4	12/12/2017	6:19 AM	KSF	<1.00	349	<500	2.67	430	Teachers Lounge	No Action Taken
CIMS5	12/12/2017	6:20 AM	KSF	<1.00	468	<500	7.84	736	Main Office	No Action Taken
CIMS6-L	12/12/2017	6:22 AM	DFD	<1.00	536	<500	<1.00	265	First Floor South Hallway	No Action Taken
CIMS6-R	12/12/2017	6:22 AM	DFD	<1.00	544	<500	<1.00	207	First Floor South Hallway	No Action Taken
CIMS7-L	12/12/2017	6:24 AM	DFD	<1.00	2910	<500	1.32	542	First Floor South Hallway @ Room 113	No Action Taken
CIMS7-R	12/12/2017	6:25 AM	DFD	<1.00	3040	<500	5.55	914	First Floor South Hallway @ Room 113	No Action Taken
CIMS8-L	12/12/2017	6:26 AM	DFD	<1.00	2390	<500	1.76	1240	First Floor South Hallway @ Room 113	No Action Taken
CIMS8-R	12/12/2017	6:27 AM	DFD	<1.00	2270	<500	1.53	493	First Floor South Hallway @ Room 113	No Action Taken
CIMS9	12/12/2017	6:29 AM	NS	<1.00	546	<500	17.0	3310	Nurse Office	Faucet not consumption source
CIMS10-L	12/12/2017	6:32 AM	DFD	<1.00	439	<500	<1.00	343	Second Floor South Hallway @ Room 212	No Action Taken
CIMS10-R	12/12/2017	6:33 AM	DFD	<1.00	701	<500	<1.00	315	Second Floor South Hallway @ Room 212	No Action Taken
CIMS11-L	12/12/2017	6:34 AM	DFD	<1.00	503	<500	<1.00	135	Second Floor North Hallway @ Room 201	No Action Taken
CIMS11-R	12/12/2017	6:35 AM	DFD	<1.00	416	<500	<1.00	97.0	Second Floor North Hallway @ Room 201	No Action Taken
CIMS12	12/12/2017	6:38 AM	DFS	<1.00	330	<500	5.90	187	First Floor Outside of Main Gym	No Action Taken
CIMS13	12/12/2017	6:40 AM	KSF	<1.00	271	<500	<1.00	700	Kitchen	No Action Taken
CIMS14	12/12/2017	6:41 AM	DFS	<1.00	561	<500	<1.00	227	First Floor Outside of Aux Gym	No Action Taken
CIMS15	12/12/2017	6:42 AM	DFS	<1.00	547	<500	<1.00	129	First Floor Outside of Aux Gym	No Action Taken
SL 15SEC	12/12/2017	5:48 AM	SL	<1.00	26.6	<500	3.32	12.1	Meter	No Action Taken
SL 45SEC	12/12/2017	5:48 AM	SL	<1.00	6.71	<500	<1.00	6.21	Meter	No Action Taken

**Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, \*SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink**

\* Service Connection Tap is not a point for consumption water