

**HEROES ACADEMY**

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
HR1	1/9/2018	6:10 AM	SC-1S	<1.00	69.5	<500	<1.00	89.6	Backflow #1	No Action Taken
HR2	1/9/2018	6:15 AM	SC-1M	<1.00	16.2	<500	<1.00	26.6	Backflow #2	No Action Taken
HR3-L	1/9/2018	6:17 AM	DFD	<1.00	160	<500	2.79	316	Main East Hallway	No Action Taken
HR3-R	1/9/2018	6:17 AM	DFD	<1.00	115	<500	1.70	142	Main East Hallway	No Action Taken
HR4	1/9/2018	6:19 AM	DFS	<1.00	220	<500	<1.00	57.1	Main Hallway Across From Office	No Action Taken
HR5	1/9/2018	6:20 AM	DFS	<1.00	279	<500	<1.00	38.6	Main Hallway Across From Office	No Action Taken
HR6-L	1/9/2018	6:21 AM	DFD	<1.00	163	<500	2.91	98.2	Gymnasium	No Action Taken
HR6-R	1/9/2018	6:22 AM	DFD	<1.00	88.0	<500	2.03	97.7	Gymnasium	No Action Taken
HR7	1/9/2018	6:23 AM	DFS	<1.00	854	<500	1.62	177	Classroom 104	No Action Taken
HR8-L	1/9/2018	6:24 AM	DFD	<1.00	1030	<500	16.0	516	Cafeteria	Disabled
HR8-R	1/9/2018	6:25 AM	DFD	<1.00	1050	<500	21.3	485	Cafeteria	Disabled
HR9-L	1/9/2018	6:25 AM	DFD	<1.00	677	<500	14.3	792	Cafeteria	Disabled
HR9-R	1/9/2018	6:25 AM	DFD	<1.00	397	<500	7.32	479	Cafeteria	Disabled
HR10	1/9/2018	6:27 AM	IM	<1.00	18.0	<500	<1.00	8.86	Kitchen Ice Maker	No Action Taken
HR11	1/9/2018	6:28 AM	KSF	<1.00	230	<500	3.94	197	Kitchen Sink	No Action Taken
HR12	1/9/2018	6:29 AM	TL	<1.00	438	<500	6.18	244	Teachers Lounge Sink	No Action Taken
HR13-L	1/9/2018	6:30 AM	DFD	<1.00	164	<500	8.88	230	North Hallway Near Classroom 116	No Action Taken
HR13-R	1/9/2018	6:30 AM	DFD	<1.00	189	<500	10.1	541	North Hallway Near Classroom 116	No Action Taken
HR14	1/9/2018	6:32 AM	DFS	<1.00	262	<500	<1.00	8.33	North Hallway Across From Auditorium	No Action Taken
HR15	1/9/2018	6:33 AM	DFS	<1.00	243	<500	<1.00	14.1	North Hallway Across From Auditorium	No Action Taken
HR16	1/9/2018	6:35 AM	DFS	<1.00	304	<500	<1.00	16.4	Second Floor West Hallway	No Action Taken
HR17	1/9/2018	6:36 AM	DFS	<1.00	255	<500	1.76	127	Second Floor West Hallway	No Action Taken
HR18	1/9/2018	6:38 AM	KSF	<1.00	502	<500	6.26	753	Wellness Center	No Action Taken
HR19-L	1/9/2018	6:42 AM	DFD	<1.00	144	<500	4.05	364	Second Floor East Hallway	No Action Taken
HR19-R	1/9/2018	6:42 AM	DFD	<1.00	94.4	<500	2.56	59.3	Second Floor East Hallway	No Action Taken
SL 15SEC	1/9/2018	5:44 AM		<1.00	34.7	<500	3.47	6.93	Meter	No Action Taken
SL 45SEC	1/9/2018	5:44 AM		<1.00	14.9	<500	1.44	4.53	Meter	No Action Taken

**Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, \*SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink**

\* Service Connection Tap is not a point for consumption water