

Irving Elementary

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
IRV1	4/5/2018	6:00 AM	SC-1S	<1.00	11.3	<500	<1.00	6.40	Backflow #1	No Action Taken
IRV2	4/5/2018	6:04 AM	SC-1M	<1.00	4.40	<500	<1.00	3.03	Backflow #2	No Action Taken
IRV3	4/5/2018	6:07 AM	KSF	<1.00	509	<500	<1.00	195	Nurses Office	No Action Taken
IRV4	4/5/2018	6:08 AM	TL	<1.00	301	<500	<1.00	348	Teachers Lounge	No Action Taken
IRV5	4/5/2018	6:10 AM	DFS	<1.00	183	<500	<1.00	56.9	Southwest Hallway near Classroom #1145	No Action Taken
IRV6	4/5/2018	6:11 AM	DFS	<1.00	115	<500	<1.00	62.5	Northwest Hallway near Classroom #1113	No Action Taken
IRV7	4/5/2018	6:13 AM	DFS	<1.00	291	<500	<1.00	60.2	Main Hallway near Music Room	No Action Taken
IRV8	4/5/2018	6:13 AM	DFS	<1.00	254	<500	<1.00	55.4	Main Hallway near Music Room	No Action Taken
IRV9	4/5/2018	6:14 AM	DFS	<1.00	232	<500	<1.00	89.7	Hallway near Gymnasium	No Action Taken
IRV10-L	4/5/2018	6:15 AM	KSF	<1.00	538	<500	<1.00	224	Kitchen	No Action Taken
IRV10-R	4/5/2018	6:15 AM	KSF	<1.00	505	<500	<1.00	243	Kitchen	No Action Taken
SL 15SEC	4/3/2018	6:14 AM		<1.00	198	<500	24.3	14.5	Meter	No Action Taken
SL 45SEC	4/3/2018	6:14 AM		<1.00	27.6	<500	3.09	6.45	Meter	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water