

South High School

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
SO1	7/13/2018	6:05 AM	SC-1S	<0.1	5.60	27	0.40	12.00	Backflow #1	No Action Taken
SO2	7/13/2018	6:08 AM	SC-1M	<0.1	3.00	14	0.20	8.00	Backflow #2	No Action Taken
SO3	7/13/2018	6:10 AM	DFS	<0.1	412.9	<5	5.70	188.0	Swimming Pool Area	No Action Taken
SO4	7/13/2018	6:13 AM	DFS	<0.3	180.3	39	17.6	959	Wood Shop	Filtration system added
SO5	7/13/2018	6:14 AM	DFS	<0.1	181.2	<.5	7.60	146	Hallway near Classroom #44	No Action Taken
SO6	7/13/2018	6:19 AM	DFS	<0.1	60.4	25	0.40	10.00	Weight Room	No Action Taken
SO7	7/13/2018	6:24 AM	DFS	<0.1	1300.00	8	2.80	38	Hallway near Varsity Locker Room	No Action Taken
SO11	7/13/2018	6:24 AM	DFS	<0.1	321.30	17	0.50	210	Hallway near Gymnasium	No Action Taken
SO12	7/13/2018	6:25 AM	DFS	<0.1	514.40	<5	1.20	105	Kitchen	No Action Taken
SO14-L	7/13/2018	6:29AM	KSF	<0.1	152.30	<5	6.80	366	Kitchen	No Action Taken
SO14-R	7/13/2018	6:30 AM	KSF	<0.1	72.40	112	7.80	400	Kitchen	No Action Taken
SO15	7/13/2018	6:31 AM	DFS	1.90	1341.70	<5	19.6	445	Cafeteria	Filtration system added
SO16	7/13/2018	6:33 AM	DFS	6.9	373.10	<5	54.4	405	Cafeteria	Filtration system added
SO17	7/13/2018	6:35 AM	DFS	0.20	399.90	<5	35.4	373	Store Room Behind Stage Area	Filtration system added
SO18	7/13/2018	6:36 AM	DFS	1.30	215.70	9	22.0	532	Hallway near Activities Office	Filtration system added
SO19	7/13/2018	6:39 AM	DFS	<0.1	282.6	6	3.20	239.0	Hallway near Auditorium	No Action Taken
SO20	7/13/2018	6:41 AM	DFS	<0.1	230.40	<5	2.80	123.0	Hallway near Auditorium	No Action Taken
SO22	7/13/2018	6:43 AM	DFS	<0.1	127.60	6	7.00	91	Hallway near Classroom #30	No Action Taken
SO23	7/13/2018	6:46 AM	DFS	<0.1	329.80	5	13.8	200	Hallway near Classroom #17	Filtration system added
SO24	7/13/2018	6:46 AM	DFS	<0.1	101.70	<5	3.80	39.0	Hallway near Classroom #17	No Action Taken
SO25	7/13/2018	6:48 AM	DFS	1.00	715.00	<5	20.9	1488	Hallway near Classroom #17	Filtration system added
SO26	7/13/2018	6:49 AM	DFS	0.20	179.10	<5	4.80	431	Hallway near Classroom #17	No Action Taken
SO27	7/13/2018	6:50 AM	DFS	2.60	67.2	25	3.40	315.0	Hallway near Classroom \$11	No Action Taken
SO28	7/13/2018	6:51 AM	DFS	<0.1	101.9	<5	5.20	94	Hallway near Classroom \$11	No Action Taken
SO30	7/13/2018	6:52 AM	DFS	<0.1	267.90	<5	13.0	146.0	Hallway near Classroom #9	No Action Taken
SO31	7/13/2018	6:54 AM	DFS	0.50	424.60	16	4.30	375	Media Center	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water