

**Sunset Park Elementary**

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
STP1	2/21/2018	5:57 AM	SC-1S	<1.00	14.3	<500	2.33	4.07	Backflow #1	No Action Taken
STP2	2/21/2018	6:03 AM	SC-1M	<1.00	6.70	<500	1.06	2.14	Backflow #2	No Action Taken
STP3	2/21/2018	6:04 AM	DFS	<1.00	137	<500	19.5	232	Classroom #20	Diabled
STP4	2/21/2018	6:06 AM	DFS	<1.00	165	<500	16.0	108	Classroom #16	Diabled
STP5	2/21/2018	6:07 AM	DFS	<1.00	298	<500	50.7	294	Classroom #17	Diabled
STP6	2/21/2018	6:08 AM	DFS	<1.00	387	<500	38.5	159	Classroom #15	Diabled
STP7	2/21/2018	6:10 AM	DFS	<1.00	655	<500	49.0	173	Classroom #10	Diabled
STP8	2/21/2018	6:13 AM	KSF	<1.00	1490	<500	1.83	688	Nurses Office	No Action Taken
STP9	2/21/2018	6:14 AM	DFS	<1.00	528	<500	<1.00	20.5	ESS Room	No Action Taken
STP10	2/21/2018	6:15 AM	TL	<1.00	971	<500	1.45	331	Teachers Lounge	No Action Taken
STP11-L	2/21/2018	6:16 AM	DFD	<1.00	85.1	<500	6.87	302	Hallway Near Gymnasium	No Action Taken
STP11-R	2/21/2018	6:16 AM	DFD	<1.00	62.6	<500	5.30	265	Hallway Near Gymnasium	No Action Taken
STP12-L	2/21/2018	6:17 AM	DFD	<1.00	70.0	<500	5.08	584	Cafeteria	No Action Taken
STP12-R	2/21/2018	6:17 AM	DFD	<1.00	76.3	<500	5.83	497	Cafeteria	No Action Taken
STP13	2/21/2018	6:19 AM	KSF	<1.00	181	<500	2.50	883	Kitchen	No Action Taken
STP14-L	2/21/2018	6:21 AM	DFD	<1.00	47.5	<500	16.8	172	Gymnasium	Diabled
STP14-R	2/21/2018	6:21 AM	DFD	<1.00	33.7	<500	6.11	152	Gymnasium	No Action Taken
STP15	2/21/2018	6:24 AM	DFS	<1.00	541	<500	3.76	192	Classroom #29	No Action Taken
SL 15SEC	2/21/2018	5:54 AM		<1.00	45.7	<500	6.48	9.99	Meter	No Action Taken
SL 45SEC	2/21/2018	5:54 AM		<1.00	37.9	<500	4.21	8.10	Meter	No Action Taken

**Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, \*SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink**

\* Service Connection Tap is not a point for consumption water